Tank Removal Nov. 13- 1990 Tank (1) 550 tout in Front of building lost Stard Sos Tonk (2) 550 Toul at front corner of building last Stared ges Tank (3) 1000 Tout at Back Command Took (1) less thon 20 feet long. Sail Somple app. It I feet under took at each End product lines yours I son more years ago Tonk (2) less than 20 feet long Sail Somple 1 to 2 feet under Each and aftents To lines Took (3) less thon De feet long Sail Sorpl 1 to 2 feet under Each end of toul 70 lines All Sorph were laker and place in glass you with Seal life then place in ice chart Than taken to lake. The analysis used (5030) November 13, 1990

REPORT OF ANALYSIS

JOB #:

HBS01107

CUSTOMER:

Hill Backhoe Service

P. O. # :

ಾಣ Brace Baptist Church

SAMPLE :


4887 GAS TANK 1 A # 4888 GAS TANK 1 B # 4889 GAS TANK 2 A # 4890 GAS TANK 2 B # 4891 GAS TANK 3 A

4892 GAS TANK 3 B

RESULTS	<u>4887</u>	<u>4888</u>	<u>4889</u>	<u>4890</u>	<u>4891</u>	<u>4892</u>
Total Petroleum Hydrocarbons (ppm) as Gasoline by	<10	<10	(10	⟨1∅	<10	⟨1∅

Guilford Laboratories, Inc.

J. A. Rayburn



FOUR SEASONS INDUSTRIAL SERVICES INCOMPOSE Post Office Box 16590 N.C. Dept. NR Greensboro, North Carolina 27416-0590

(919)273-2718

N.C. Dept. NRCD

DEC 14 1990

Winston-Salem Regional Office

TANK DISPOSAL MANIFEST

1)	Tank Owner/Authorized Representative: Name and Mailing Address						
	LAND A Hill SA	xT3 Box 692 Tm	vity Ne				
	27370 TANKS From	NEW Grad Baptis	T CHUN AH				
2)	Tank Owner/Authorized Representativ	e: Phone No. ()					
3)	Description of Tanks: Tank No. Capacity	Previous Contents Com	ments				
	/ /000	wast iil					
	1 500	′1					
	1 510	"					
4)	storage tanks have been removed from the	Tam Brown	at the above listed				
	. "	Signature	<u> </u>				
5)	Four Seasons Industrial Services facility	hat the above listed storage tanks have been at 519 Patton Ave. Greensboro, N.C.	transported to the				
	Printed/Typed Name	Signature	Month Day Year				
6)	Decontamination Manager: The unders cleaned and scrapped.	signed certifies that the above listed storage to	anks have been				
	Printed/Typed Name	Signature Signature	//- 7-9 Month Day Year				
7)	Disposal Certification: The undersigne into scrap pieces and accepted by the me	ed certifies that the above-named storage tanketal recycling facility.	(s) have been cut				
	Recycling Facility:	·	·				
	Rolect 7 welds Printed/Typed Name	Signature	1/ 8-90 Month Day Your				
	т ппеш турей маше	Signature	Month Day Year				

Kivile dr River dale Ra